

AD-A037 548

NAVAL AIR DEVELOPMENT CENTER WARMINSTER PA AIR VEHICL--ETC F/G 1/3
DETERMINATION OF THE AIRWORTHINESS OF ZPG-3W COTTON D621 AND TH--ETC(U)
JAN 77 E T VADALA
NADC-76322-30

UNCLASSIFIED

NL

| OF |
AD
A037 548



END

DATE
FILMED
4-77

ADA 037548

REPORT NO. NADC-76322-30

12
B.S.



DETERMINATION OF THE AIRWORTHINESS OF ZPG-3W COTTON D-621
AND THE ZPG-2 DACRON GDC-5 AIRSHIP ENVELOPES

Eleanor Th. Vadala
Air Vehicle Technology Department
NAVAL AIR DEVELOPMENT CENTER
Warminster, Pennsylvania 18974

31 JANUARY 1977

FINAL REPORT

DDC
RECEIVED
MAR 31 1977
A

[Handwritten signature]

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED

AD No.
DDC FILE COPY

Prepared for
NAVAL AIR SYSTEMS COMMAND
Department of the Navy
Washington, D.C. 20361

NOTICES

REPORT NUMBERING SYSTEM - The numbering of technical project reports issued by the Naval Air Development Center is arranged for specific identification purposes. Each number consists of the Center acronym, the calendar year in which the number was assigned, the sequence number of the report within the specific calendar year, and the official 2-digit correspondence code of the Command Office or the Functional Department responsible for the report. For example: Report No. NADC-76015-40 indicates the fifteenth Center report for the year 1976, and prepared by the Crew Systems Department. The numerical codes are as follows:

CODE	OFFICE OR DEPARTMENT
00	Commander, Naval Air Development Center
01	Technical Director, Naval Air Development Center
02	Program and Financial Management Department
07	V/STOL Program Office
09	Technology Management Office
10	Naval Air Facility, Warminster
20	Aero Electronic Technology Department
30	Air Vehicle Technology Department
40	Crew Systems Department
50	Systems Department
60	Naval Navigation Laboratory
81	Technical Support Department
85	Computer Department

PRODUCT ENDORSEMENT - The discussion or instructions concerning commercial products herein do not constitute an endorsement by the Government nor do they convey or imply the license or right to use such products.

APPROVED BY:

D. M. STURM
Commander, USN
Deputy Director, AVTD

DATE:

31 January 1977

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER 14 NADC-76322-30	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) DETERMINATION OF THE AIRWORTHINESS OF ZPG-3W COTTON D621 AND THE ZPG-2 DACRON GDC-5 AIRSHIP ENVELOPES.		5. TYPE OF REPORT & PERIOD COVERED FINAL REPORT
7. AUTHOR(s) E. Th. VADALA		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Air Vehicle Technology Department Naval Air Development Center Warminster, Pennsylvania 18974		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE 31 January 1977
		13. NUMBER OF PAGES 12 44p.
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Two nonrigid airship envelopes were removed from storage at NAS, Lakehurst, New Jersey., where they were placed in 1961. The envelopes were inspected to determine their suitability for further flight service. These were a ZPG-3W 1,496,000 cu. ft. cotton envelope (D621) and a ZPG-2 975,000 cu. ft. Dacron envelope (GDC-5). The inspection consisted of internal and external visual examination and removal and tests of specimens. The ZPG-3W envelope was found to be extensively damaged due to conditions under which		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE
S/N 0102-014-6601

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

407 209

Cont'd

next
page

JP

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

20. (Cont'd)

→ it was stored. It was judged irreparable and was scrapped. The ZPG-2 envelope was in good condition generally. An area of the upper surface exhibited low interply adhesion and reinforcement of that portion was recommended prior to applying loads of any magnitude. The envelope was considered to be suitable for further flight service when reinforcement of the upper surface was accomplished. ↗

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

S U M M A R Y

During March 1976, two nonrigid airship envelopes, formerly used with airship models ZPG-3W and ZPG-2, were removed from storage and inspected to determine their suitability for further flight service. The two envelopes had been in storage at the NAS (Naval Air Station), Lakehurst, New Jersey since 1961 and were subject to an adverse environment of occasional rain soaking, and uncontrolled temperature and humidity.

The ZPG-3W airship cotton envelope D-621, design volume of 1,496,000 cubic feet, was examined first and found to be extensively deteriorated. The deterioration was of such a nature and extent that the envelope was judged irreparable and was scrapped.

On examination, the ZPG-2 airship Dacron envelope (GDC-5), design volume of 975,000 cubic feet was found to be in good condition generally. An area of the upper surface exhibited low interply adhesion. It was recommended that the area of low interply adhesion be reinforced or replaced prior to use. The envelope was considered to be suitable for further flight service following repair of the upper surface and providing that the loading conditions and stresses involved in use do not exceed design values.

TABLE OF CONTENTS

	<u>Page No.</u>
SUMMARY	1
LIST OF TABLES	3 - 4
LIST OF FIGURES	4
INTRODUCTION	5 - 6
HISTORY AND BACKGROUND	6 - 7
EQUIPMENT AND MATERIALS	7
EXAMINATION TECHNIQUES AND FINDINGS	7 - 8
Visual Inspection	8 - 9
Laboratory Testing	9 - 10
Electron Microscopy Examination.	11
Instrumental Analysis and Solubility Tests	11
REPAIRS	11 - 12
DISCUSSION	12 - 13
RESULTS	13
CONCLUSIONS	14
RECOMMENDATIONS	14
ACKNOWLEDGEMENTS.	15
REFERENCES.	16
APPENDIX A.	A-1

L I S T O F T A B L E S

<u>Table No.</u>	<u>Title</u>	<u>Page No.</u>
I	Results of Visual Inspection of GDC-5, Gores A to P, Panels 1 through 31	17
II	Results of Visual Inspection of GDC-5, Gores A to P, Panels 32 through 62.	18
III	Results of Visual Inspection of GDC-5, Gores A to P, Panels 63 through 93.	19
IV	Results of Visual Inspection of GDC-5, Gores A to P, Panels 94 through 123	20
V	Test Results of Specimens from Sample Discs from the ZPG-3W, Cotton Envelope, D-621	21
VI	Comparison of Test Results of Specimens from the ZPG-3W, Cotton Envelope, D-621 Tested by NADC (1976) and GAC (1959).	22 - 23
VII	Physical Test Results of Fabric Discs from Patterns 24H, 44I, 67H and 87I of the ZPG-2 Dacron Envelope GDC-5.	24
VIII	Physical Test Results of Sample Disc 39I, 42I, 43H, 43I, 50D, 52D and 68I from the ZPG-2 Dacron Envelope GDC-5.	25
IX	Physical Test Results of Test Disc Sample from Each of the Ballonets	26
X	ZPG-2 Dacron Envelope GDC-5 1976 Test Data (NADC and RML) Compared to the Original 1960 (GDC) Test Values	27 - 28
XI	NAVAIRDEVCEEN 1976 Test Data Compared to the Original 1960 (GDC) Test Values	29
XII	Physical Test Results of Dacron - Neoprene Repair Fabric, Code N 313A130	30
XIII	Summary of Surface Preparation for Cementing.	31
XIV	Preparations for Mixtures of 1451-C Adhesive System	32

LIST OF TABLES

<u>Table No.</u>	<u>Title</u>	<u>Page No.</u>
XV	Permanent Repairs Made on the ZPG-2 Dacron Envelope, GDC-5	33
XVI	Permanent Repairs Made on the Ballonets of the ZPG-2 Dacron Envelope, GDC-5	34

LIST OF FIGURES

Figure 1	Water Blisters Present under a Taped Seam in the ZPG-2W Dacron Envelope, GDC-5.	35
Figure 2	Photomicrographs of Specimens from the ZPG-2 Dacron Envelope, GDC-5	36

I N T R O D U C T I O N

A ZPG-3W and a ZPG-2 airship envelope were placed in storage at the NAS, Lakehurst since 1961 and 1962 when the Navy discontinued the use of airships as operational aircraft. The ZPG-3W envelope was a cotton fabric type 1,496,000 cubic feet in volume, with manufacturer's Serial Number D-621. The ZPG-2 was a 975,000 cubic feet Dacron (polyester) type, Serial Number GDC-5.

These envelopes were stored in the envelope storage fingers of the Fabric Shop, Building No. 123 which was specifically designed for such purposes and was originally equipped to maintain controlled environmental conditions. During the 14 years of storage, however, efforts to furnish a controlled atmosphere stopped; the air conditioning equipment had been removed. In addition, the building itself was in need of repair. Hence, both envelopes were subjected to temperature and humidity variations produced by climatic changes and to accumulations of rainwater from leaks in the roof.

Because of recent interest in the Navy in new uses for LTA vehicles such as reconnaissance, transportation, and heavy lift operations, a possible need was seen for employing the stored envelopes in experimental programs. Preliminary examinations of the envelopes were made while they were in storage. These included removal of a few specimens of fabric for physical tests. On the basis of these tests, reference (a), and the visual appearance of the fabric, it was concluded that a full and detailed inspection was warranted to determine airworthiness and the NAVAIRDEVCCEN (Naval Air Development Center) was charged by the NAVAIRSYSCOM (Naval Air Systems Command) (AIR 03P3) to conduct the inspection.

The detailed inspection was performed primarily by personnel from NAVAIRDEVCCEN and National Aeronautics and Space Administration Headquarters, assisted by personnel from the United States Air Force Range Measurement Laboratory.

On removal from storage and during the "unrolling" the ZPG-3W cotton hull was found to contain large quantities of water within the folds especially concentrated on the top center area. The forward and aft ends had been folded into and laid on the center top.

The aft end of the envelope had the characteristic musty smell of mildew and the fabric was uniformly stained with the naturally produced pigments of mildew. Mildew had fed on the cotton fabric of the aft end completely rotting and weakening the fabric.

Other fabric areas, in contact with water, were similarly stained but to a lesser degree. Sample fabric discs were removed from both stained and unstained areas. Physical tests confirmed the degradation of the strength in the stained areas.

The decision was made to scrap the ZPG-3W envelope and to validate the airworthiness of the ZPG-2 Dacron envelope, (GDC-5).

On removal from storage, and after the unfolding, the center top of the ZPG-2 hull (GDC-5) was found to be wet. The inspection consisted of internal and external examination and removal and test of specimens. The GDC-5 envelope was in good condition generally. An area of the upper surface exhibited low interply adhesion.

HISTORY AND BACKGROUND

1. ZPG-3W Cotton Envelope D-621

The ZPG-3W cotton envelope was constructed in 1959 - 1960 by the Goodyear Aerospace Corporation (formerly Goodyear Aircraft Corporation) of a two ply cotton neoprene material; a bias outer ply and a straight inner ply. The basic dimensions were 85 feet by 403 feet, reference (b). The panels and gore seams of the envelope were bonded, double stitched and taped. There were four ballonets within the envelopes; one forward, one aft and two amidship. The ballonets were constructed of a two ply neoprene coated nylon fabric. All fabrics were designed for operation in temperatures from 25⁰ F. to 140⁰ F.

The D-621 envelope was built as a spare as part of the contract for the ZPG-3W airships. Upon delivery to the Navy, it was placed in storage at Lakehurst. The envelope log could not be located and therefore a detailed service history is not available.

2. ZPG-2 Dacron Envelope GDC-5

The GDC-5 was constructed by the General Development Corporation (no longer in business) in 1960 of a two ply neoprene coated Dacron polyester fabric bonded together with neoprene and neoprene hypalon (aluminum) coating on the surface; a bias outer ply and a straight inner ply. The four ballonets were constructed of a two ply lightweight nylon.

The envelope was configured for use with either a ZPG-2 or ZPG-2W type airship installation. The ZPG-2/2W was a smaller airship envelope than the ZPG-3W; 75 feet by 339 feet.

A compilation of data on the GDC-5 was obtained from H. Walker, reference (c). The information was garnered from O&R (Overhaul and Repair) inventories, status tests and the airship flight logs.

The GDC-5 was completed 10 November 1960. The airship was delivered and placed in storage in December 1968.

The envelope was first erected on airship ZPG-2, No. 141560 in 1960. Envelope GDC-5 was modified to the ZPG-2 configuration prior to its inflation.

Between March and June 1961, the ZPG-2, No. 141460 (with envelope GDC-5) logged 56 flights or a total of 694.1 flight hours.

On 30 June 1961, all fleet airship flight activity was halted and ZPG-2, No. 141560 was decommissioned and envelope GDC-5 was stored. Two research and development airships remained in flight status. One of these, the ZPG-2, No. 141561, remained in service for 14 more months. On 2 August 1961, No. 141561 was ordered transferred from Naval Air Development Unit, South Weymouth to Lakehurst for assignment to Airship Test and Development Squadron. Envelope GDC-5 was installed on ZPG-2, No. 141561. After GDC-5 was installed, the ZPG-2, No. 141561 airship made 61 flights through August 1962 logging 618.2 flight hours. Many of the components including the envelope of ZPG-2, No. 141561 were stored at NAS, Lakehurst following its decommissioning.

Summing up the entire service, the GDC-5 envelope has logged 1,312.3 total flight hours on the two airships with 117 flights.

EQUIPMENT AND MATERIALS

When the airship components were placed in storage at NAS, Lakehurst in 1961, the Navy technology of the O&R of airships came to a complete halt. Consequently, it was not surprising that many problems and difficulties were encountered in amassing the needed equipment, materials and personnel to undertake the task of inspecting an airship.

Little in the way of equipment for airship envelope maintenance and inspection was known to be available at NAS, Lakehurst. Through the cooperation of station personnel, a few experienced airship O&R technicians were located, some of whom still retained the tools used in the O&R of airships.

Both cotton and Dacron repair materials were supplied by the Goodyear Aerospace Corporation. Fortunately, useable material of the proper weight and strength still existed in sufficient quantities.

A detailed list and description of the equipment and tools used during the inspection are presented in the Appendix.

EXAMINATION TECHNIQUES AND FINDINGS

Two methods of examination were used to determine the condition and airworthiness of the envelope: (1) Visual inspection and (2) Laboratory testing of samples removed from the envelope.

The necessary manpower (70 - 80 persons) necessary to move, unroll and position the envelope were employed through a contractor, reference (e). The work was divided into three phases as follows:

Phase I - Unroll envelope and position for preliminary inspection.

Phase II - Reposition envelope for further inspection to other side of envelope.

Phase III - Fold the envelope for return to storage.

1. Visual Inspection

The visual inspection was conducted to determine the condition of the envelope fabric, security of bonded seams and to determine any injury to the fabric. Visual inspection included the examination of the surface of the envelope fabric, and the seams, inside and outside the envelopes. The permanently attached ballonets and airlines were also examined, inside and outside.

a. ZPG-3W Cotton Envelope D-621

The D-621 had been stored in a configuration wherein the fore and aft ends had been folded in and laid on the surface of the top center area. After unrolling, it was observed that pools of water were present on the surface of the top center area; the fore and aft ends were wet.

The aluminum-hypalon surface had changed to a bronze color and some cracking of the coating had occurred.

Stained and discolored areas were observed; these occurred in the areas where water had laid or where the fabric had been in contact with the water.

The aft end of the envelope had the characteristic musty odor of mildew and contained the largest area of stained and discolored fabric. On close examination, it was found that the cotton in the aft end had been completely digested, undoubtedly by mildew micro organisms. Nothing remained of the original two ply cotton except the neoprene which was very elastic. The slightest finger pressure created a hole in this area.

b. ZPG-2 Dacron Envelope GDC-5

The GDC-5 had been stored in a configuration similar to the D-621; the forward and aft ends folded into and in contact with the top center area. Again on unfolding, evidence of the presence of moisture was found; the top center area was wet.

The visual inspection was conducted by a group of eight divided into four teams of two each.

A complete inspection report is presented in Tables I, II, III and IV.

In general, the surface of the fabric had a good silver color and appeared to be that of a new fabric. Areas in the top center and the aft and forward ends were, however, discolored and contained a yellowish-green surface deposit. In these same areas, blisters under the tapes were observed and some had trapped water inside, Figure 1. The presence of trapped water was verified in that water spurted out of blisters when pierced with a knife point. During the time the envelope was on the deck, many of the blisters dried. Dried blisters are also seen in Figure 1.

Damage from handling during transport occurred in pattern 38P.

The envelope was partially inflated with air to facilitate the inspection of the inside. The ballonets were entered from the helium chamber by slitting open the access panels.

Inspections of the ballonets were conducted by two person teams; one person was inside and the second person was on the outside carrying a bright light. The outside person passed the light over the ballonet, pattern by pattern, holding the light approximately 8 - 10 inches from the fabric. The person on the opposite side checked for the transmission of the light. Pin holes in the fabric appeared as bright points of light. The ballonet fabric appeared to be in excellent condition. Three holes were found: (1) In the forward ballonet and (2) and (3) in the center port ballonet.

The access slits from the helium chamber were left open for future use.

Load sleeves, access sleeves, inspection sleeves, ECM antenna sleeves, etc., were not inspected.

2. Laboratory Testing

Laboratory testing of sample discs, removed from the envelope, were conducted to determine the strength and permeability characteristics of the fabric at the time of inspection.

Physical tests were conducted in accordance with references (f) and (g); one inch wide specimens were used to enable the maximum number of tests for a given sample disc.

a. ZPG-3W Cotton Envelope D-621

During the removal of the first sample disc from one of the stained areas, panel 41/gore E, it was noted that the fabric cut with ease. The removed sample disc tore easily with very slight hand pull. Four other test discs were removed, two each from stained and unstained areas. The test results are presented in Table V.

The cotton fabric in the aft end was completely deteriorated. While this cotton condition was fairly local, the physical tests indicated degradation. Specimens from the stained and discolored patterns showed degradation of strength and increased permeability. The stained and discolored areas were undoubtedly evidence of the effect of mildew. Those patterns not subject to mildew, unstained, showed good retention of physical properties, Table VI.

b. ZPG-2 Dacron Envelope GDC-5

Initially, four test discs, spaced over intervals of the top of the Dacron envelope, were removed and tested. The test disc included one from the discolored area (44H).

Examination of the test results, Table VII, indicated that test specimens from the 44H sample disc exhibited extremely low interply adhesion. An effort was made to determine the extent of the poor ply adhesion keeping in mind the need to limit sampling to as few as possible without limiting any critical area. A simple peel test was devised that consisted of the following procedure: (1) a thin-bladed knife was carefully inserted between the two plies of fabric; (2) two parallel cuts, separated by one inch were made on the outer fabric; and (3) a horizontal cut connected the parallel ones thereby forming a tongue. The "tongue" was pulled back. The following patterns were tested with this peel test: (1) 39I; (2) 42I (discolored), (3) 43I (discolored); (4) 43H (slightly discolored); (5) 48I; (6) 52D; (7) 60I and (8) 67H. Of these peel tests, those close to the 44H pattern that exhibited low interply adhesion, behaved in a similar manner. The "tongue" of the 42I, 43I and 43H discolored I patterns peeled back with very little effort and one surface of the ply interface was clean. Test discs were removed from these patterns. The "tongue" of the remaining peel tests required great effort to pull back. These patterns were judged to have good interply adhesion. Sample test discs 43H and 52D were tested by the United States Air Force Range Measurement Laboratory and the results are presented in reference (h). There was good agreement between their test data and the test results of NAVAIRDEVCON, Table VIII. Low interply adhesion was shown by the test specimens from the sample discs in proximity to pattern 44H.

Test specimens were heated for 16 hours at 100°F to determine if temperature would improve the interply adhesion. Two specimens showed a slight improvement in the ply adhesion and two, a decrease in the ply adhesion, Table VII. Because of the inconclusiveness of these results; no further temperature tests were conducted.

A sample disc was removed from each of the four ballonets. The test results are presented in Table IX.

The results of the fabric tests at the time of manufacture were entered in the envelope manufacturer's log, reference (i). Each roll of fabric had been assigned an individual identification number. The envelope manufacturer's log lists the envelope number, every pattern in the envelope and the number of the roll from which each was cut.

The currently generated physical test data is compared to the original test values, Tables X and XI. The original test values were obtained by consulting the manufacturer's log to find the number of the roll from which the pattern in question was cut. The original test data was then located in the laboratory test records. Examination of the test results shows excellent retention of strength and permeability.

Physical tests were conducted on the Dacron-neoprene repair fabric, Table XII.

3. Electron Microscopy Examination

An electron microscopy examination was made by the Range Measurement Laboratory. The photomicrographs, Figure 2, show that the neoprene pulled off the polyester monofilaments of the better ply adhesion test specimens with difficulty, leaving pull marks (irregular mottled spots). These pulled marks are raised deformations caused by tension. No such pull marks appear on the monofilaments of test specimens with low ply adhesion.

4. Instrumental Analysis and Solubility Tests

Efforts were made to identify the yellowish material deposited on the surface of the fabric with discolored patterns. Infra-red analysis indicate that the material was of inorganic structure; no organic structure was identified. Emission spectroscopy for metallic constituents indicated that the material was predominately of a silicate nature; an inorganic. Microscopic examination further confirmed the inorganic nature of this material.

Solubility tests indicated that the material was insoluble in the solvents used, behaving in a manner similar to vermiculite, a hydrated silicate material.

It is hypothesized that this material is the residue of the talcum powder used to destroy the tack of the excess cement. The dusting powder is a hydrated magnesium silicate, an inorganic material.

R E P A I R S

Repairs consisted primarily of installing patches over cut-outs from which test specimens had been removed.

The repair materials included: (1) polyester (Dacron) two ply fabric (Code N 313-A-130); (2) polyamide (Nylon) two ply fabric (Code N 288-A-220); and (3) Adhesive system (1451 cement and accelerators 983 and 1467C).

The Dacron fabric was of similar weight, strength and permeability to the NH 311E76-15A fabric originally used for the envelope, Table XII. The compatibility of bonding the Dacron fabric to the envelope fabric with the 1451 adhesive system was tested and reported to be satisfactory, reference (j).

The Nylon fabric from current stock was of similar strength and permeability to the N 202B34 fabric originally used. No physical tests were made of this repair fabric due to the limited amount of material.

All repairs to the airship fabrics involved the preparation of the repair materials and the cleaning and preparation of fabric surfaces. These procedures are thoroughly discussed in references (d), Section V, (k) and (l). The specific preparation procedures used for the different surfaces encountered were done in accordance with Table XIII. Trichlorethane 1.1.1 (stabilized) solvent was used. Scotch-Brite was used to buff the surface of the fabric.

In making repairs on the Dacron fabric, it was necessary to use a second accelerator, the 1467-C, to ensure a proper bond. The proper preparations are shown, Table XIV, for the three different mixtures: (1) extra light, (2) light; and (3) heavy.

Nine coats of adhesive were applied to the mating surfaces as follows:

- (1) First and second coats - extra light mixture.
- (2) Third and fourth coats - light mixture.
- (3) Fifth to ninth coats - heavy mixture.

Repair procedures are presented in Section V of reference (d). Patches were placed on the inside and outside of areas requiring repair. Table XIII and XVI include a complete tabulation of the repairs made to the fabric envelope and ballonets.

DISCUSSION

ZPG-3W - It was obvious that the deterioration of the ZPG-3W envelope was caused by bacteriological attack on the natural fiber (cotton) of the fabric. Such evidence as was actually evaluated by specimen removal, and other visual checks was sufficient to indicate to the inspection team that major portions of the envelope were in similar condition and extensive sampling would have been necessary to locate the usable portions. Repairs would have been required to such extent so as to exceed the available supply of materials with no guarantee of 100% airworthiness. It was on this basis that the envelope was scrapped.

ZPG-2 - The discolored patterns of the ZPG-2 were in contact with water. Test specimens from these patterns showed low ply adhesion, and a "clean" peel at the interface.

Neoprene compounds can be affected by moisture. Data, reference (n), available on life jackets and other multiple plies of bonded fabrics, suggest that under conditions of moderate temperature and moisture, neoprene compounds exhibit a phenomena of a loss of adhesion at the interface.

Neoprene and hypalon plus heat degradation or oxidation will yield sulphur, carbon dioxide and hydrogen chloride. The hydrogen chloride in combination with moisture produces hydrochloric acid which attacks the adhesion at the interface. Instead of a cohesive failure where some of the adhesive sticks to each side of the interface, the break at the interface is clean. The adhesive adheres to one side and the other side is "clean".

The Range Measurement Laboratory, reference (h), hypothesized that the poor adhesion was caused by hydrolytic deterioration of the surface of the polyester yarns monofilaments. The electron photomicrographs do not verify that the weak adhesion of the neoprene interply is the result of such hydrolytic decomposition. The photomicrographs, however, do show that the neoprene pulled off the areas of good ply adhesion with difficulty leaving "pull marks" evidenced by the irregular mottled spots. Tension between the plies probably caused these deformations. In contrast, the specimens with poor ply adhesion did not show any "pull marks" but the surface of the polyester monofilaments were smooth.

It was agreed that small but finite tension is provided by neoprene "interlocking" through the interstices of the weave.

There is also data available that when accelerators are used in excess, they will also combine with moisture to cause the breakdown of the adhesion value at the interface. A clean pull will occur between the adhesive and the fabric interface.

The current test data suggests that the low interply adhesion seems to be confined to the top two patterns of the hull (gore H and I) and extends from panel 40 to panel 63. There is also some evidence of poor ply adhesion in the aft and forward ends.

R E S U L T S

Visual inspection indicated that in general the bonded areas in the ZPG-2 Dacron envelope GDC-5 were intact and the fabric showed little damage.

Laboratory tests of specimens from the sample discs removed from the envelope indicated that, at the time of test, the permeability and strength characteristics were good showing little change from the original test values. The interply adhesion, however, showed deterioration. This deterioration of ply adhesion was especially marked in the discolored areas.

Electron photomicrographs showed that the neoprene in the "better" ply adhesion areas pulled off with difficulty, leaving pull marks. In comparison the areas of poor ply adhesion did not show any pull marks.

Efforts to identify a yellowish surface deposit indicated that the material was of inorganic nature, a siliceous material, probably the talcum powder used to destroy the excess tack of the adhesive system.

CONCLUSIONS

In general, the inside and outside of the envelope fabric and the ballonets (forward, aft, center port and starboard) of the GDC-5 appeared to be in excellent condition.

Physical test results showed little deterioration in the strength and permeability characteristics. Deterioration, however, was evident in the interply adhesion and was particularly marked in the center top gores. The poor ply adhesion was confined to a very limited area and will require future repair. The ZPG-2 GDC-5 Dacron envelope appears to be airworthy.

Personnel from NASA, Range Measurement Laboratory and NAVAIRDEVCEEN agreed that the center areas exhibiting low ply adhesion would have to be reinforced or replaced. The exact method of repair would be determined prior to actual commitment to use. The envelope was considered to be in an acceptable condition for further flight use following such repair, provided that the loading conditions and stresses involved in such use did not exceed design values.

RECOMMENDATIONS

It was recommended by the inspection team that the areas of the ZPG-2 Dacron envelope GDC-5 exhibiting low ply adhesion be reinforced or replaced. The exact method of repair should be determined prior to actual commitment to use. The loading conditions and stresses should not exceed design values.

It was further recommended that the airship hull be subjected to a full pressure test to ensure the integrity of the seams.

It was strongly recommended that the envelope be stored in an area that will be safe from rain soaking and with controls on the temperature and humidity.

A C K N O W L E D G E M E N T S

The author wishes to acknowledge the valuable assistance of Mr. Norman Meyers of NASA Headquarters without whom this program could not have been successfully completed.

Acknowledgement is further extended to the following for their assistance:

Mr. Edward Crosby, RCA employee under contract to the United States Air Force Eastern Test Eange, Patrick Air Force Base, Florida

The staff and employees of the Naval Air Station, Lakehurst, New Jersey, with a special appreciation to Mr. James Manuel and the employees of the Public Works Department.

LtCol Lewis of the Army Aviation Detachment who made hangar space available.

Mr. William Zarkowski, Crew Systems Department, who provided the materials and had the air tubes fabricated.

R E F E R E N C E S

- (a) Meyers, D. N., "Tests of Fabric Samples from ZPG-3W and ZPG-2W Airship Envelopes", Report 97-Y-1, Serial No. 001, Piasecki Aircraft Corp., Philadelphia, Pennsylvania
- (b) SD-457-3W-1, "Detail Specification for Model ZPG-3W Airship", Serial No. 112, Department of Navy, Bureau of Aeronautics, dated 12 Apr 1956
- (c) Private communication from Mr. Hepburn Walker, Jr. to Mr. John Eney, dated 15 Mar 1976
- (d) NAVWEPS 01-195-503, "Repair Manual - Airship Envelope Fabrics for Airship Models, including ZPG-2, ZPG-2W, ZPG-3W dated 1 Apr 1961
- (e) Contract No. N62269-76-C-0321 with M&T Company, Philadelphia, Pennsylvania dated 8 Mar 1976
- (f) Military Specification MIL-C-21189 (AER) Amendment 1, Cloth Laminates, ZPG-2 and ZPG-2W Type Airship Envelope" dated 15 Jul 1959
- (g) GER 7688, "LTA Specification for Testing Coated Airship Fabrics", Code Indent No. 2500, Goodyear Aerospace Corporation dated 20 Nov 1956
- (h) "Letter form Report of Tests on Fabric Samples from GDC-5 Blimp Hull" E. L. Crosby, Jr. dated 19 Mar 1976
- (i) Report No. R 600 B-5, "Fabric Data for ZPG-2W Airship Envelope (Contract N383-57782A), Envelope GDC-4 and -5, dated 16 Mar 1960
- (j) Telephone conversation between Mr. G. Faurote Goodyear Aerospace Corp. and Miss E. Th. Vadala of Naval Air Development Center of 12 Mar 1976
- (k) Code Indent No. 25500, Process Specification CI, Goodyear Aerospace Corp.
- (l) Rev. J, Amendment 2, Process Specification CI, "Adhesives, General Specification for Application Of", Goodyear Aerospace Corp.
- (m) GER 8126, "Fabric Data for ZPG-3W Airship Envelopes" Goodyear Aircraft Corp. dated 28 Mar 1957

TABLE I
RESULTS OF VISUAL INSPECTION OF GDC-5, GORES A TO P, PANELS 1 THROUGH 31

Gore	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P
Panel																
1																W
2																W
3																W
4																W
5																W
6																W
7																W
8									L							W
9									L							W
10																W
11																W
12																W
13																W
14																W
15																W
16																W
17																W
18																W
19																W
20																W
21																W
22																W
23																W
24																W
25																W
26																W
27																W
28																W
29																W
30																W
31																W
B - Blister																
C - Chafing																
D - Defective Tape																
H - Hole																
H* - Hole, Ripped and Torn																
L - Loose Tape																
T - Trapped Water																
W - Water Stain																
() - Loose Cover Patch																

TABLE II
RESULTS OF VISUAL INSPECTION OF GDC-5, GORES A TO P, PANELS 32 THROUGH 62

Gore	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P
Panel																
32																
33																
34																
35																
36																
37																
38																
39																
40																
41																
42																
43																
44																
45																
46																
47																
48																
49																
50																
51																
52																
53																
54																
55																
56																
57																
58																
59																
60																
61																
62																

TABLE III
RESULTS OF VISUAL INSPECTION OF GDC-5, GORES A TO P, PANELS 63 THROUGH 93

<u>Gore</u>	<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>	<u>E</u>	<u>F</u>	<u>G</u>	<u>H</u>	<u>I</u>	<u>J</u>	<u>K</u>	<u>L</u>	<u>M</u>	<u>N</u>	<u>O</u>	<u>P</u>
<u>Panel</u>																
63																
64																
65																
66																
67																
68																
69																
70																
71																
72																
73																
74																
75																
76																
77																
78																
79																
80																
81																
82																
83																
84																
85																
86																
87																
88																
89																
90																
91																
92																
93																

L

TABLE IV

RESULTS OF VISUAL INSPECTION OF GDC-5, GORES A TO P, PANELS 94 THROUGH 123

Gore	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P
Panel																
94																
95																
96																
97								*								
98								*								
99								*								
100								*								
101								*								
102								*								
103								*								
104								*								
105								*								
106								*								
107								*								
108								*								
109								*								
110								*								
111								*								
112								*								
113								*								
114								*								
115								*								
116								*								
117								*								
118								*								
119								*								
120								*								
121								*								
122								*								
123								*								

* Defective Cement (crystallized)

TABLE V
TEST RESULTS OF SPECIMENS FROM SAMPLE DISCS FROM THE ZPG-3W, COTTON ENVELOPE, D-621

Panel/Gore		40I Slight Stain	40H Unstained	41I Strongly Stained	84I Unstained
Tensile Strength (lbs./in.) Straight Warp	1	182	247	54	225
	2	180	237	60	213
	3	185	223	77	218
	Avg.	182	236	64	219
Filling	1	155	294	30	191
	2	183	198	52	190
	3	167	225	44	186
	Avg.	168	239	42	189
Bias Warp	1	145	190	No	199
	2	152	194	Test	217
	Avg.	148	192		208
Fill	1	238	215	No	205
	2	164	188	Test	206
	Avg.	201	201		205
Weight (oz./yd. ²)		29.6	28.0	25.3	26.0
Helium Permeability L/sq. m/24hrs.	1	56	3.6	Over	2.4
	2	108	1.7	400	2.0
	3	210	11.0		2.3
	Avg.	125	5.4	Over 400	2.2
Ply Adhesion	1	13.2	15.8	No	14.8
	2	9.8	15.0	Test	11.2
	Avg.	11.5	15.4		13.0

TABLE VI
COMPARISON OF TEST RESULTS OF SPECIMENS FROM THE ZPG-3W, COTTON ENVELOPE,
D-621 TESTED BY NADC (1976) AND GAC (1959)

Panel/Gore	<u>40I</u>		<u>40H</u>		<u>41I</u>		<u>84I</u>		
	Slightly Stained	Unstained	Unstained	Badly Stained	Unstained				
Original Fabric Identification	N 113 A520	N 113 A530	N 113 A520	N 113 A520	N 113 A510	N 113 A510			
Fabric Roll No.	8472	8470	8465	8483					
Tested by:	<u>NADC</u>	<u>GAC</u>	<u>NADC</u>	<u>GAC</u>	<u>NADC</u>	<u>GAC</u>			
Tensile Strength(lbs./in.)									
Straight Warp	1	182	Not available	247	Not available	54	200	225	210
	2	180		237		60	220	213	212
	3	<u>185</u>		<u>223</u>		<u>77</u>	<u>228</u>	<u>218</u>	<u>212</u>
	Avg.	182		<u>236</u>		<u>64</u>	<u>223</u>	<u>217</u>	<u>211</u>
Filling	1	155	Not available	294	Not available	30	235	191	218
	2	183		198		53	238	190	210
	3	<u>167</u>		<u>225</u>		<u>44</u>	<u>230</u>	<u>186</u>	<u>208</u>
	Avg.	168		<u>239</u>		<u>42</u>	<u>234</u>	<u>189</u>	<u>212</u>
Bias Warp	1	145	Not available	190	Not available	No test	210	199	212
	2	<u>152</u>		<u>194</u>			<u>215</u>	<u>217</u>	<u>215</u>
	Avg.	148		<u>192</u>			<u>213</u>	<u>208</u>	<u>214</u>
Fill	1	238	Not available	215	Not available	No test	234	205	247
	2	<u>164</u>		<u>188</u>			<u>241</u>	<u>206</u>	<u>251</u>
	Avg.	201		<u>201</u>			<u>238</u>	<u>205</u>	<u>249</u>

TABLE VI (Cont'd)

COMPARISON OF TEST RESULTS OF SPECIMENS FROM THE ZPG-3W, COTTON ENVELOPE,
D-621 TESTED BY NADC (1976) AND GAC (1959)

Panel/Gore	<u>40I</u>		<u>40H</u>		<u>41I</u>		<u>84I</u>	
	Slightly Stained		Unstained		Badly Stained		Unstained	
	NADC	GAC	NADC	GAC	NADC	GAC	NADC	GAC
Weight (oz/yd. ²)	29.6	Not available	28.0	Not available	25.3	25.25	26.0	24.10
Helium Permeability L/sq. m/24 hrs.	1 56	Not available	3.6	Not available	Over 400	3.4	2.4	3.8
	2 108		1.7			2.8	2.0	3.1
	3 210		<u>11.0</u>		<u>12.4</u>	<u>2.3</u>	<u>2.3</u>	<u>3.1</u>
	Avg. 125		5.4		Over 400	3.1	2.2	3.3
Ply Adhesion	1 13.2	Not available	15.8	Not available	No test	13.3	14.8	14.5
	2 9.8		<u>15.0</u>			<u>14.3</u>	<u>11.2</u>	<u>14.8</u>
	Avg. 11.5		15.4			13.3	13.0	14.7

TABLE VII

PHYSICAL TESTS RESULTS OF FABRIC DISCS FROM PATTERNS 24H, 44I, 67H
AND 87I OF THE ZPG-2 DACRON ENVELOPE GDC-5

Panel/Gore	24H	44H*	67H	87I
Tensile Strength (lbs./in.)				
Straight Warp	315	300	265	305
	316	286	275	299
	<u>310</u>	<u>289</u>	<u>289</u>	<u>297</u>
	Avg.	314	292	276
			276	300
Fill	274	260	253	294
	273	256	250	295
	<u>266</u>	<u>262</u>		<u>290</u>
	Avg.	271	259	252
			252	293
Bias Warp	210	210	196	217
	179	212	206	206
			<u>200</u>	
	Avg.	194	211	201
			201	212
Fill	190	149**	177	195
	210	162**	164	189
			<u>185</u>	
	Avg.	200	156	175
			175	192
Helium Permeability L/sq. m/24hrs.	0.8	1.1	0.9	0.6
Ply Adhesion (lbs./in.)	7.1	2.0***	6.8	10.4

* Discolored with yellowish white deposit.

** Ply separation observed.

*** Approximated value.

TABLE VIII

PHYSICAL TEST RESULTS OF SAMPLE DISC 39I, 42I, 43H, 43I, 50D, 52D, AND 68I
FROM THE ZPG-2 DACRON ENVELOPE GDC-5

Panel/Gore	39I	42I	43I	43H	50D	52D	68I
Tested by	NADC	(Discolored) NADC	(Discolored) NADC	Range Measurement Lab.	Range Measurement Lab.	NADC	NADC
Tensile Strength (lbs./in.)							
Straight Warp	293	296	293	303	282	290	298
	285	298	296	297	272	290	302
	288		287	306	283	294	306
				312	284		
	Avg.	297	292	305	280	291	302
Fill	262	258	252	267	267	263	283
	266	258	250	263	272	241	283
	265		240	269			285
	Avg.	258	247	266	270	252	281
Bias	264	197				214	
Warp		203				213	
	Avg.	200				214	
Fill		160				201	
		160				172	
		160				187	
Ply Adhesion		Warp	Fill				
	4.8	2.8	1.5	1.85	-	9.2	5.4
(lbs./in.)	5.5	2.8	1.4	2.0		9.3	6.5
		2.4		1.9			
				1.95			
				1.9			
				1.9			
After 16 hrs. at 100 F	Avg.	2.6	2.2			9.3	6.0
Helium Permeability	5.0	3.4	-	-	-	7.3	6.2
L/sq. m/24 hrs.	1.0	1.2	1.2	0.889	0.889	0.6	0.9
	1.3	1.1	1.0	0.9004	0.9004	0.6	0.9
	1.1	0.8	0.8				0.8
	1.1	1.0	1.0			0.6	0.9
Weight (oz./yd. ²)	15.73	31	16.90	16.32	16.14	-	15.73

TABLE IX

PHYSICAL TEST RESULTS OF TEST DISC SAMPLE FROM EACH OF THE BALLONETS

<u>Ballonet Identification</u>	<u>Forward</u>	<u>Aft</u>	<u>Center Port</u>	<u>Center Starboard</u>
Panel/Gore	39I	72A	55B	57B
Tensile Strength (lbs./in.)				
Straight Warp	128	126	194	177
	125	125	186	177
	121	125	180	177
	Avg. <u>125</u>	<u>125</u>	<u>186</u>	<u>177</u>
Fill	121	120	178	163
	117	123	178	164
	111	121	172	164
	Avg. <u>116</u>	<u>121</u>	<u>176</u>	<u>164</u>
Ply Adhesion (lbs./in.)	3.8	3.2	4.2	7.0
Helium Permeability	No ¹	0.4	1.0	0.3
L/sq. m/24 hrs.	test	0.4	0.9	0.3
		0.4	1.0	0.1
		<u>0.4</u>	<u>1.0</u>	<u>0.2</u>
Weight (oz./yd. ²)	6.09	6.44	8.00	8.76

¹ Torn sample, could not be tested for permeability.

BEST AVAILABLE COPY

TABLE X
ZPG-2 DACRON ENVELOPE GDC-5 1976 TEST DATA (NADC AND RSL) COMPARED TO THE ORIGINAL 1960 (GDC) TEST VALUES

Panel/Core	8L	24H	39I	42I	43H	43I	43 Car Canopy
Original Fabric Identification	NH 311 E76-15A	NH 311 Re 76-15A	NH 311 LE76-15A	NH 311 E76-15A	NH 311 F76-15A	NH 311 F76-15A	NH 311 E61-15
Fabric Roll No.	251	271	260	230	252	252	145
Data Generated by:	Test Original NADC GDC	Test Original NADC GDC	Test Original NADC GDC	Test Original NADC GDC	Test Original NADC GDC	Test Original NADC GDC	Test Original NADC GDC
Tensile Strength (lbs./in.)	Test Original NADC GDC	Test Original NADC GDC	Test Original NADC GDC	Test Original NADC GDC	Test Original NADC GDC	Test Original NADC GDC	Test Original NADC GDC
Straight Warp	292 284 281	315 316 310	282 287 300 300 300 304	296 298 298 275 275 272	296 282 280 275 285 262	293 296 287 275 285 262	222 240 235 236 232 235 238 235
Avg.	286	314	296	297	292	292	236
Fill	267 250 259	273 266 274	300 300 290 287 250 295	258 258 255 255 255 256	265 275 267 265 250 258	252 250 240 265 250 258	221 229 233 236 240 251 231
Avg.	259	271	295	256	266	247	272
Ply Adhesion (lbs./in.)	3.6 3.8	12.5 13.0 14.7	7.5 7.5 7.5 9.5 9.0 8.3	6.2 6.2	4.8 5.5	2.2 2.1	9.8 10.1
Straight Warp	3.7	11.2	8.7	6.2	5.1	14.2 14.6 15.3 13.4 13.6 15.3 14.4	11.0 14.0 15.0 15.0 15.0 16.0 14.4
Helium Permeability	0.9 0.8 0.9	0.7 0.3	0.3 2.0 1.2	0.7 0.7	1.0 1.3 1.1	1.2 1.0 0.8 1.0	1.0 1.2 1.0 1.0
L/sq. m/24 hrs.	16.68	16.11	15.82	15.73	15.90	16.11 16.9 16.11	15.2 15.79
Avg.	16.68	16.11	15.82	15.73	15.90	16.11 16.9 16.11	15.2 15.79
Weight (ozs./yd ²)							

TABLE X
 CPG-2 LACRON ENVELOPE GDC-5 1976 TEST DATA (NADC AND EML) COMPARED TO THE ORIGINAL 1960 (GDC) TEST VALUES (CONTINUED)

Panel/Core	44H		56 Car Capacity		50D		52D		67H		68I		87I	
	NH 311 E76-15A	NH 311 E61-15	NH 311 E76-15A	NH 311 E76-15A	NH 311 E76-15A	NH 311 E76-15A	NH 311 E76-15A	NH 311 E76-15A	NH 311 E76-15A	NH 311 E76-15A	NH 311 E76-15A	NH 311 E76-15A	NH 311 E76-15A	NH 311 E76-15A
Original Fabric Identification														
Fabric Roll No.	230	149	218	218	218	218	218	218	220	220	262	262	265	265
Data Generated by:	Test	Original	Test	Original	Test	Original	Test	Original	Test	Original	Test	Original	Test	Original
	NADC	GDC	NADC	GDC	NADC	GDC	NADC	GDC	NADC	GDC	NADC	GDC	NADC	GDC
Tensile Strength (lbs./in.)	300	280	243	222	272	272	290	272	265	275	300	300	303	275
	286	265	240	240	275	275	290	275	275	275	300	300	299	287
Straight Warp	299	265	247	264	263	263	294	277	289	287	300	300	297	283
		275		232	284	280	280	280	287	287	305	305	282	282
Avg.	292	272	243	238	280	280	291	272	276	275	293	293	300	257
		273		235				287		279				275
Fill	260	228	228	221	267	240	263	240	253	245	275	275	294	275
	256	217	217	229	272	242	241	242	250	275	290	290	290	275
Avg.	262	226	226	233		247		247	262	262	280	280	285	285
		240		240		252		252	270	270	280	280	285	285
Ply Adhesion (lbs./in.)	259	256	224	251	270	246	232	246	252	265	281	280	293	275
				231		242		242						
Straight Warp	1.2	20.5	9.8	11.0	No test	18.2	8.4	18.2	7.0	22.5	5.4	10.8	10.4	13.4
	2.0	20.4	10.0	14.0		19.5	7.3	19.5	6.8	24.0	6.5	11.2	11.0	15.6
Avg.		19.5		15.0		20.0		20.0		25.6		14.3	11.2	15.7
		10.0		15.0		12.6		12.8		18.2		8.0	8.0	16.4
Helium Permeability		9.8		15.0		15.0		15.0		21.0		8.0	8.0	17.2
		16.5		15.0		15.1		15.1		21.2		7.4	7.4	17.3
L/aq. m/24 hrs.	0.9	0.4	0.8	2.0	0.899	1.2	0.6	1.2	No test	1.8	0.9	.3	.7	.8
	1.2	0.9	0.4	1.8	0.904	1.4	0.6	1.4		1.1	0.9	.2	.6	.5
Avg.	1.1	0.7	0.6	1.9	0.89	1.3	0.6	1.3		1.5	0.9	0.3	0.9	0.7
Weight (ozs./yd. ²)	No test	16.03	15.9	15.79	16.14	14.98	No test	14.98	No test	15.40	15.73	15.79	No test	15.98

TABLE XI

29

TABLE XII

PHYSICAL TEST RESULTS OF DACRON - NEOPRENE REPAIR FABRIC, CODE N 313A130

Dacron - Neoprene Fabric Code No.	N 313-A-130
Tensile Strength (lbs./in.)	
Straight Warp	279 277 <u>291</u> 279
Fill	253 250 <u>240</u> 248
Bias Warp	257 276 <u>265</u> 264
Fill	232 245 <u>230</u> 236
Adhesion Between Plies (lbs./in.)	9.4 <u>7.3</u> 8.4
Helium Permeability L/sq. m/24 hrs.	0.4 0.4 <u>0.4</u> 0.4
Weight (oz./yd ²)	15.66

TABLE XIII
SUMMARY OF SURFACE PREPARATION FOR CEMENTING

NOTE NAVWEPS 01-195-503 Section V

Any surface completely prepared for repairs must be dry, clean, reasonably smooth; free from oil or paraffin, reasonably free from paints and pebbled-cement, uniform in color, and free from streaks.

SURFACE	REMOVE	EXTENT	PROCESS	FINISHED APPEARANCE	PAR. REF.
a. Plain NOTE Remove sheen on Dacron fabrics before cementing.	Curing dust	All	Scrub surface* and wash surface with cloth dampened with tolnaphtha solution, Solvesso, trichloroethane 1.1.1 (stabilized), or toluene.	Dark coat is free from dirt streaks and has a velvety appearance and feel.	5-24 5-25
b. Paraffined	Paraffin	All	Buff surface* with fiber bristle brush and wash surface with cloth dampened with trichloroethane 1.1.1 (stabilized).	Dark coat is free from dirt streaks and pin-points of light. Surface has a velvety appearance and feel.	5-26 5-27
c. Aluminized	Neoprene aluminum paint	Reasonably free of paint coat	Buff surface* and wash surface with cloth dampened with tolnaphtha solution, Solvesso, trichloroethane 1.1.1 (stabilized), or toluene.	Dark grey finish is free from dirt streaks and has even color. Surface has a velvety feel.	5-28 5-29 5-30
d. Exposed (cement-pebbled)	Old cement	Reasonably free of cement	Rub surface with fabric eraser*; wash with cloth dampened with tolnaphtha solution, Solvesso, trichloroethane 1.1.1 (stabilized), or toluene.	Some cement may be firmly attached to surface. Surface is fairly smooth and of an even color.	5-31 5-32
e. Painted with anti-static coating	Anti-static coating and paraffin (refer to "b")	All	Buff surface* and wash surface with cloth dampened with trichloroethane 1.1.1.	Dark coat is free from dirt streaks and has a velvety appearance and feel.	5-32A
f. Coated with anti-radiation paint	Anti-radiation coating and paraffin (refer to "b")	All	Buff surface* and wash surface with cloth dampened with tolnaphtha or trichloroethane 1.1.1 (stabilized).	Dark coat is free from dirt streaks and has a velvety appearance and feel.	5-32D
g. Hypalon-aluminum weather-resistant paint	Hypalon paint down to neoprene coating	All	Rub surface with fabric eraser*; wash with cloth dampened with tolnaphtha solution, Solvesso, or trichloroethane 1.1.1 (stabilized).	Dark grey finish is free from dirt streaks and has even color.	5-30A 5-30B

TABLE XIV

PREPARATIONS FOR MIXTURES OF 1451-C ADHESIVE SYSTEM

<u>Ingredient</u>	<u>Heavy Mixture</u>	<u>Light Mixture</u>	<u>Extra-Light Mixture</u>
Neoprene Cement (1451-C)	1.00 gallon	1.00 gallon	1.00 gallon
Accelerator (983-C)	100 cc	100 cc	100 cc
Accelerator (1467-C)	None	None	200 cc
Trichloroethane 1.1.1 (stabilized)	None	0.33 gallon (43 fluid oz.)	0.50 gallon (64 fluid oz.)

TABLE XV

PERMANENT REPAIRS MADE ON THE ZPG-2 DACRON ENVELOPE, GDC-5

<u>Test Disc</u>	<u>Test Disc Car Cover</u>	<u>Peel Test (Tongue Test)</u>	
Panel/Gore			Batten patch 18 H and I
8L			Hole in antenna plate 44/H
24H			Handling damage - oblong patch 37/H
39I			Piasecki test sample, 35/F
42H, 42I			
43H, 43I	43		Holes: 55B
44H		44H, 44H	56M
	46		56B (5)
		48I	81P
50D, 50D			Large oblong hole in air tunnel
50M			
52D			
53D		60I	
67H		67H	
68I			
87I			
117J			


TABLE XVI

PERMANENT REPAIRS MADE ON THE BALLONETS OF THE ZPG-2 DACRON ENVELOPE, GDC-5

<u>Test Disc From Ballonet</u>	<u>Panel/Gore</u>
Forward	39P; Hole part of 20% mark
Center - Starboard	57B; Hole near Panel 56, 12' above shoe Hole near Panel 57 - high
Center - Port	55B
Aft	72A



Figure 1. Water Blisters Present under a Taped Seam in the
ZPG-2W Dacron Envelope, GDC-5



Specimen from Sample Disc with Good Ply Adhesion



Specimen from Samples Disc with Low Ply Adhesion

Figure 2. Photomicrographs of Specimens from the ZPG-2
Dacron Envelope GDC-5, (552X)

NADC-76322-30

APPENDIX A

NADC-76322-30

APPENDIX A

The equipment and material items included the following:

1. Items Purchased, on Hand or in Stock

Blower - used to inflate the envelope for overhaul work and to supply a constant flow of fresh air; capable of delivering 500 cubic feet of air per minute and operated on 115 volts A.C.

Brush, paint flat hair bristle brush used to apply adhesive (cement) system.

Brush, wire - copper bristle brush used to buff fabric surface to prepare for application of adhesive (cement) system.

Crayon, marking - wax crayon used to mark test discs on the envelopes during inspection for repairs. Crayons used were soluble in 1,1,1 trichloroethylene.

Foot Covers - foot coverings made of coated heavy muslin and worn while working on either the inflated or deflated envelopes. The foot covers were placed over shoes while on the ground cloth to prevent the dirt on the shoes coming in contact with the envelope. The foot covers were removed before leaving the ground cloth.

Lamp Guards - used to prevent any breakage of bulbs from falling in the vicinity of fabric repair activity.

Lamp, heat standard infra-red bulb mounted in explosive-proof housing used to hasten drying and curing of adhesive system.

Roller - rubber faced roller used to roll patches when installing on the envelope.

Roller - steel faced roller used to roll patches when installing on the envelope; available in widths of 1, and 1-1/2 inches.

Solvent, stabilized 1,1,1 trichloroethylene - used as washing solution for cleaning ballonet fabric and envelope fabric, inside and outside prior to repair.

Stitcher - a 1/4 inch wide steel roller. It is used to securely position patch prior to rolling.

Talcum Powder - hydrated magnesium silicate used to destroy the tack of excess cement.

Tape, masking - 3 inch wide cloth tape, 60 yards to a roll.

Tube socks were utilized as foot covers in place of rigger moccasins by the personnel who assisted in unrolling, moving and positioning the envelope. The tube socks were placed over shoes or socks while on ground cloth to prevent scuff damage to the envelope. The tube socks were removed before leaving the ground cloth.

2. Items Fabricated

Air Tubes - open end cylindrical tubes (2) measuring 18-1/2 inches by 75 feet were made of lightweight nylon.

Tunnel Frames, access - 42 inch wide by 60 feet long steel frames.

Cloth, Ground - assembled of 8 ozs. 72 inches wide E duck and masking tape to provide a protective ground cloth for the airship envelopes. The cloth was greater in size than the deflated envelope.

Templates - for test discs and repair patches.

(1) Test disc - plywood template consisting of two concentric circles, 12 inch and 15 inches in diameter.

(2) Repair patch - bristol board template approximately 15 inch in diameter alternately notched and scalloped on the outer edge.

3. Repair Fabrics and Neoprene Adhesive (Cement) Systems (identified with Goodyear Aerospace Corp., codes).

1. Repair Fabric

a. Cotton-neoprene fabric for repair of the ZPG-3W cotton envelope D-621.

(1) Code N 113-A-120 fabric.

(2) Code N 113A-520 fabric.

b. Dacron-neoprene fabric for repair of the ZPG-2 Dacron polyester envelope GDC-5.

(1) Code N 313-A-130 fabric

c. Nylon fabric for ballonnet repair.

(1) Code N-228-A-220 fabric.

2. Neoprene Adhesive Systems

a. Two part neoprene-adhesive system for the
ZPG-3W cotton envelope:

1451 Cement with 983 accelerator.

b. Three part cement system for the ZPG-2 Dacron
polyester envelope GDC-5:

1451 Cement with 983 accelerator and
1467-C accelerator.

D I S T R I B U T I O N L I S T

REPORT NO. NADC-76322-30

	<u>No. of Copies</u>
NAVAIRSYSCOM (AIR-954).	4
(2 for retention)	
(1 for AIR-03P3)	
(1 for OP-05B) (RADM C. J. Seiberlich)	
DDC	12